

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector: Matthew 0				
Inspection Date:	spection Date: Thursday, February 13, 2020 Project Contact: Br		Brian Claut	Brian Clauto,		
Spread I: Franklin	MP 269-269.6 ATWS 523, 693, 693A, 351, 351A MLV-AR-32	Weather:	Rainy			
ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)						
☐ Tree Felling	☐ Clearing/Grubbing ☐ Gra	ding	ning		Stri	nging/Welding
☐ Lowering/Backfilling ☐ Final Grading ☐ Temp. Stabilization ☐ Perm. Stabilization				\boxtimes	□ Dormant	
				Yes	No	N/A
Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?				\boxtimes		
Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?					\boxtimes	
3. Areas of offsite sediment deposition observed?					\boxtimes	
 <u>Comments:</u> Inspected the following resources: S-HH4, S-F11, S-C20, S-C19 ECD's were in place and functioning at the designated crossings. Routine Maintenance: (<u>72-Hour Deadline</u> from Notification) N/A Ineffective Controls: (<u>24-Hour Deadline</u> from Notification) St14219+80 sump triple stack has undermined and requires repair. Recommended Corrective Action: Maintain and install all controls per the approved PSS&S. 						

<u>Deadline:</u> Within 24-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____

Date: Thursday, February 13, 2020



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline <u>Date</u>: Thursday, February 13, 2020

Figure 1: St14219+80 sump triple stack has undermined and requires repair



 Figure 2: Designated crossing S-HH4, ECD's are in place



<u>Figure 3</u>: Designated stream S-C19, ECD's are in place.



Figure 4: Designated stream S-F11, ECD's are in place.

