

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, April 25, 2019	Project Contact:	Brian Clauto
Spread I: Pittsylvania County	STA 15826+88 – STA 15947+64	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-G2, W-G2, S-B2, S-H55 and S-H54.

STA 15884+02: Repair bridge underlayment fabric.
 STA 15905+00: Stabilize rill erosion.
 STA 15922+50: Stabilize rill erosion/clean out sump.
 STA 15924+60: Stabilize ATWS 611.
 STA 15924+70 – STA 15929+00: Stabilize stockpiles and area outside travel lane.
 STA 15945+00: CFS and P1 undermined.
 STA 15947+00: Stabilize slope.
 STA 15947+00: Stabilize area.

Recommended Corrective Action: Maintain and install all controls per the approved plan and specs.

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: 04/25/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, April 25, 2019

Fig. 1: STA 15884+02 – Bridge underlayment damaged.



Fig. 2: STA 15905+00 – Stabilize erosion.



Fig. 3: STA 15922+50 – Sump needs maintenance.



Fig. 4: STA 15924+60 – Stabilize.



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, April 25, 2019

<p>Fig. 5: STA 15924+70 – STA 15929+00 – Stabilize stockpiles and areas outside travel lane in ATWS 611.</p> <div style="border: 1px solid black; padding: 2px; margin-bottom: 5px;"> 320°NW (T) 36°50'24"N, 79°21'58"W ±32.8ft ▲ 655ft </div>  <div style="display: flex; justify-content: space-between; font-size: x-small; margin-top: 5px;"> Stabilize stockpiles/erosion ATWS 611 25 Apr 2019, 11:37:24 </div>	<p>Fig. 6: STA 15945+00 – CFS and P1 undermined.</p> <div style="border: 1px solid black; padding: 2px; margin-bottom: 5px;"> 59°NE (T) 36°50'14"N, 79°21'43"W ±16.4ft ▲ 603ft </div>  <div style="display: flex; justify-content: space-between; font-size: x-small; margin-top: 5px;"> CFS/P1 undermined 15945 25 Apr 2019, 11:49:01 </div>
<p>Fig. 7: STA 15947+00 – Stabilize slope.</p> <div style="border: 1px solid black; padding: 2px; margin-bottom: 5px;"> 127°SE (T) 36°50'14"N, 79°21'39"W ±7963.0ft ▲ 593ft </div>  <div style="display: flex; justify-content: space-between; font-size: x-small; margin-top: 5px;"> Stabilize slope 15947 25 Apr 2019, 11:52:17 </div>	<p>Fig. 8: STA 15947+00 – Stabilize area.</p> <div style="border: 1px solid black; padding: 2px; margin-bottom: 5px;"> 43°NE (T) 36°50'14"N, 79°21'41"W ±16.4ft ▲ 607ft </div>  <div style="display: flex; justify-content: space-between; font-size: x-small; margin-top: 5px;"> Stabilize area 15947 25 Apr 2019, 11:53:30 </div>