

Archived: Tuesday, July 19, 2016 10:28:37 AM
From: Glassman, Joseph (DEQ)
Sent: Tuesday, July 19, 2016 10:11:00 AM
To: 'Jason P Ericson (Services - 6)'
Cc: Chapman, Randy (DEQ); John Black (VirginiaPower - 1); Jason E Williams (Services - 6); Amanda B Tornabene (Services - 6); John D Dicarlo (VirginiaPower - 1); Brett W Paulin (Services - 6); Paula A Hamel (Services - 6); Erica L Stratton (Services - 6)
Subject: RE: Crystal Substation and Roaches Run Weekly Update: July 18, 2016
Importance: Normal

Jason,

DEQ approves your request to remove the booms from Roaches Run. Let me know if you have any other questions or issues.

Joe Glassman
Environmental Specialist
Virginia Department of Environmental Quality
Northern Regional Office
13901 Crown Court
Woodbridge, VA 22193
703-583-3808
joseph.glassman@deq.virginia.gov
www.deq.virginia.gov

From: Jason P Ericson (Services - 6) [mailto:jason.p.ericson@dom.com]
Sent: Monday, July 18, 2016 12:38 PM
To: Glassman, Joseph (DEQ)
Cc: Chapman, Randy (DEQ); John Black (VirginiaPower - 1); Jason E Williams (Services - 6); Amanda B Tornabene (Services - 6); John D Dicarlo (VirginiaPower - 1); Brett W Paulin (Services - 6); Paula A Hamel (Services - 6); Erica L Stratton (Services - 6)
Subject: Crystal Substation and Roaches Run Weekly Update: July 18, 2016

Mr. Glassman,

As requested in your February 23, 2016 letter, below is the weekly update for activities at the Crystal Substation and at Roaches Run/Gravelly Point. We are now conducting inspections once per week. We are currently maintaining boom in the vicinity of Outfall #2 into Roaches Run. We have not observed oil or sheen at this outfall in recent inspections and request approval to permanently remove the remaining boom. Based on our discussion last week, you will relay our request to the other members of the Unified Command. Please let us know if you need additional information.

If you have any questions please contact John Black or me.

**Crystal Substation Daily
Inspection Notes: July 18, 2016**

Thursday 10:30 am July 14 (mid tide) – Storm water drop inlet outside the Station showed no signs of oil or sheen. Roaches Run outfall showed no signs of oil. Absorbent boom was changed as a precaution. Gravelly Point boat launch area showed no amounts of sheen. Roaches Run parking area showed no signs of sheen. No dye was noted at any of the inspection areas.

Thank you,
Jason

Jason P. Ericson, PG
Dominion Resources Services, Inc.
Environmental Policy
5000 Dominion Blvd
Glen Allen, VA 23060
Phone: (804) 273-3012
Mobile: (804) 317-9464
Fax: (804) 273-2964

CONFIDENTIALITY NOTICE: This electronic message contains information which may be legally confidential and or privileged and does not in any case represent a firm ENERGY COMMODITY bid or offer relating thereto which binds the sender without an additional express written confirmation to that effect. The information is intended solely for the individual or entity named above and access by anyone else is unauthorized. If you are not the intended recipient, any disclosure, copying, distribution, or use of the contents of this information is prohibited and may be unlawful. If you have received this electronic transmission in error, please reply immediately to the sender that you have received the message in error, and delete it. Thank you.