

Archived: Tuesday, June 14, 2016 11:57:51 AM

From: Jason P Ericson (Services - 6)

Sent: Monday, June 13, 2016 1:21:54 PM

To: Glassman, Joseph (DEQ)

Cc: Chapman, Randy (DEQ); John Black (VirginiaPower - 1); Jason E Williams (Services - 6); Amanda B Tornabene (Services - 6); John D Dicarlo (VirginiaPower - 1); Brett W Paulin (Services - 6); Paula A Hamel (Services - 6)

Subject: Crystal Substation and Roaches Run Weekly Update: June 13, 2016

Importance: Normal

Mr. Glassman,

As requested in your February 23, 2016 letter, below is the weekly update for activities at the Crystal Substation and at Roaches Run/Gravelly Point.

If you have any questions please contact John Black or me.

Thank you,
Jason

Jason P. Ericson, PG
Dominion Resources Services, Inc.
Environmental Policy
5000 Dominion Blvd
Glen Allen, VA 23060
Phone: (804) 273-3012
Mobile: (804) 317-9464
Fax: (804) 273-2964

**Crystal Substation Daily
Inspection Notes and Summary: June 13, 2016**

Summary Monday June 6 – Friday June 10: A sheen was observed on one day, Monday June 6, at the boat launch area at Gravelly Point. No other sheen or oil was noted at any of the other inspection points.

Below you will find our daily observations for inspections:

Monday 1:45 pm June 6 (low tide) – The storm water drop inlet outside the Station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil. Gravelly Point boat launch area showed a slight sheen in small areas, which was likely the result of heavy boat traffic. Roaches Run parking area showed no signs of oil or sheen.

Tuesday 12:40 pm June 7 (high tide) – The storm water drop inlet outside the Station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil. Gravelly Point boat launch area showed no signs of oil or sheen at the docks or edge of water. Roaches Run parking area showed no signs of oil or sheen.

Wednesday 12:40 pm June 8 (high tide) – The storm water drop inlet outside the Station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil. Gravelly Point boat launch area showed no signs of oil or sheen. Roaches Run parking area showed no signs of oil or sheen.

Thursday 11:30 am June 9 (mid tide) – The storm water drop inlet outside the Station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil. Absorbent boom at outfall #2 was changed as a precaution. Gravelly Point boat launch area showed no signs of oil or sheen. Roaches Run parking area showed no signs of oil or sheen.

Friday 8:05 am June 10 (low tide) – The storm water drop inlet outside the Station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil. Gravelly Point boat launch area showed no signs of oil or sheen. Roaches Run parking area showed no signs of oil or sheen.

Jason P. Ericson, PG
Dominion Resources Services, Inc.
Environmental Policy
5000 Dominion Blvd
Glen Allen, VA 23060
Phone: (804) 273-3012
Mobile: (804) 317-9464
Fax: (804) 273-2964

CONFIDENTIALITY NOTICE: This electronic message contains information which may be legally confidential and or privileged and does not in any case represent a firm ENERGY COMMODITY bid or offer relating thereto which binds the sender without an additional express written confirmation to that effect. The information is intended solely for the individual or entity named above and access by anyone else is unauthorized. If you are not the intended recipient, any disclosure, copying, distribution, or use of the contents of this information is prohibited and may be unlawful. If you have received this electronic transmission in error, please reply immediately to the sender that you have received the message in error, and delete it. Thank you.