

Archived: Tuesday, March 29, 2016 9:40:46 AM

From: Jason P Ericson (Services - 6)

Sent: Friday, March 25, 2016 9:26:39 AM

To: Glassman, Joseph (DEQ)

Cc: Amanda B Tornabene (Services - 6); Chapman, Randy (DEQ); John Black (VirginiaPower - 1); John D Dicarlo (VirginiaPower - 1); Cathy C Taylor (Services - 6); Jason E Williams (Services - 6)

Subject: Crystal Substation and Roaches Run Weekly Update: March 24, 2016

Importance: Normal

Mr. Glassman,

As requested in your February 23, 2016 letter, below is the weekly update for activities at the Crystal Substation and at Roaches Run/Gravelly Point. If you have any questions please contact John Black or me.

Thank you,
Jason

Jason P. Ericson, PG
Dominion Resources Services, Inc.
Environmental Policy
5000 Dominion Blvd
Glen Allen, VA 23060
Phone: (804) 273-3012
Mobile: (804) 317-9464
Fax: (804) 273-2964

**Crystal Substation Daily
Inspection Notes and Summary: March 24, 2016**

Summary Friday, March 18 – Thursday, March 24: No oil of any kind was observed in the storm water drop inlet outside the Station this week. Only minor sheen and small pockets of emulsified oil has been observed at Gravelly Point boat dock area. The Roaches Run outfall absorbent boom is still riding high in the water and collecting only trash and pollen, no signs of oil or sheen. This absorbent boom was changed out on Thursday, March 24th. The yellow hard boom, owned by Miller Environmental, in Roaches Run down stream of the outfall will remain as a precaution. All other absorbent boom and hard boom has been removed from Gravelly Point and 3rd outfall at the RR tracks. Much less sheen and emulsified oil was observed as we progressed through the week. Also, we did not observe any accumulations of water or oil in vaults inside or outside station this week.

Below you will find our daily observations for inspections:

Friday March 18; 1:00 pm (low tide) – Storm water drop inlet outside the Station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil. Gravelly Point boat launch area showed no signs of oil or sheen. All hard boom in this area is removed. Roaches Run parking area showed no signs of oil or sheen.

Saturday March 19; 9:00 am (tide going out) – Storm water drop inlet outside the Station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil. Gravelly Point boat launch area had small pockets of emulsified oil along the shore in the rocks. Roaches Run parking area showed no signs of sheen, but a couple of small pockets of emulsified oil were observed.

Sunday March 20; 8:30 am (high tide) – Storm water drop inlet outside the Station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil. Gravelly Point boat launch area had small pockets of emulsified oil along the shore in the rocks. Roaches Run parking area showed no signs sheen or emulsified oil.

Monday March 21; 11:30 am (tide going out) – Storm water drop inlet outside the Station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil. Gravelly Point boat launch area showed no signs of oil or sheen. Roaches Run parking area showed no visible sheen or oil present. All inside electrical vaults were inspected and found to be dry not requiring to be pumped out. All containment liners for all four transformers are completed and we pumped out 750 gallons of rain water from the 4 lined containments.

Tuesday March 22; 10:30 am (tide going out) – Storm water drop inlet outside the Station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil. Gravelly Point boat launch area showed no signs of oil or sheen. Roaches Run parking area showed very small amounts of sheen present around some leaf litter. Vaults inside station were empty.

Wednesday March 23; 11:30 am (low tide) – Storm water drop inlet outside the Station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil. Gravelly Point boat launch area showed no signs of oil or sheen. Roaches Run parking area showed no signs of sheen. Vaults inside station were empty.

Thursday March 24; 8:00 am (tide going out) – Storm water drop inlet outside the Station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil, and absorbent boom changed out. Gravelly Point boat launch area showed no amounts of sheen. Roaches Run parking are showed no signs of sheen. Vaults inside station were empty.

Jason P. Ericson, PG
Dominion Resources Services, Inc.
Environmental Policy
5000 Dominion Blvd
Glen Allen, VA 23060
Phone: (804) 273-3012
Mobile: (804) 317-9464
Fax: (804) 273-2964

CONFIDENTIALITY NOTICE: This electronic message contains information which may be legally confidential and or privileged and does not in any case represent a firm ENERGY COMMODITY bid or offer relating thereto which binds the sender without an additional express written confirmation to that effect. The information is intended solely for the individual or entity named above and access by anyone else is unauthorized. If you are not the intended recipient, any disclosure, copying, distribution, or use of the contents of this information is

prohibited and may be unlawful. If you have received this electronic transmission in error, please reply immediately to the sender that you have received the message in error, and delete it. Thank you.