




Geosyntec
consultants

APPENDIX H

Seep Investigation Photograph Log




Picture 1.- View of PRGS sheet-pile bulkhead from south beach area facing north



Picture 2. - View of PRGS sheet-pile bulkhead from north beach area facing south



Picture 3. - View of PRGS sheet-pile bulkhead noting position of Seep B and Seep C



Picture 4. - View of north-side PRGS sheet-pile bulkhead noting position of Outfalls 003, 009, 010 and Seep A locations



Picture 5. - View of Outfall 010 and adjacent Seep A



Picture 6. - View of Seep D located on north-side bulkhead section approaching concrete wall of Screen House





Picture 7.- View of south-section of PRGS sheet-pile bulkhead facing north, noting position of Seep E and Seep F.




Picture 8.- View of south-section of PRGS sheet-pile bulkhead, noting area south Seep F approaching south beach area.




Picture 9.- View of south-section of PRGS sheet-pile bulkhead toward south beach area.




Picture 10: Seep A, with and without thermal imaging




Picture 11: Seep B, with and without thermal imaging




Picture 12: Seep C, with and without thermal imaging



Picture 13: Seep D, with and without thermal imaging



Picture 14: Seep E, with and without thermal imaging



Picture 15: Seep F, with and without thermal imaging