

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, January 30, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Giles County	STA 11236+21 – 11159+86 STA 10929+71 – 10971+74 MVP-GI-249.01/249.02/242.01	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following ATWS: 1370, 1347, 1331 and 467.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Thursday, January 30, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, January 30, 2020

Figure 1: STA 11227+00 – Controls in place and functioning properly. Area stabilized with straw.

☉ 122°SE (T) ● 37°16'55"N, 80°23'49"W ±42653.0ft ▲ 1318ft



Figure 2: STA 11203+00 – Controls in place and functioning properly. Area stabilized with straw.

☉ 143°SE (T) ● 37°18'15"N, 80°30'25"W ±164.1ft ▲ 2234ft



Figure 3: STA 10970+00 – Controls in place and functioning properly. Area with straw.

☉ 293°W (T) ● 37°19'14"N, 80°37'57"W ±16421.4ft ▲ 3001ft



Figure 4: STA 10932+00 – Controls in place and functioning properly. Area stabilized with straw.

☉ 301°NW (T) ● 37°19'50"N, 80°34'51"W ±164.1ft ▲ 2259ft

