

FIELD INSPECTION

| | | | |
|--|--------------------------|--------------------------------|---------------|
| Project Name: | Mountain Valley Pipeline | Inspector: | Matthew Grant |
| Inspection Date: | Thursday, March 21, 2019 | Project Contact: | Brian Clauto |
| Spread: Montgomery County MP225-226 | Spread G | Weather (Wet/Dry/Rain): | Dry |

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: Dormant

Yes No N/A

- 1 Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?
- 2 Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?
- 3 Areas of offsite sediment deposition were observed?


Comments:

- ECD's and stabilization are functioning between St#11932+54 and 11961+00

Recommended Corrective Action: n/a

Deadline: n/a

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:  Date: 3-28-19

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, March 21, 2019

- Fig. 1 Near St#11932+54 permanent waterbar has been installed and area has been stabilized



- Fig. 2 At karsts feature 226.42, ECD's are in place and functioning



- Fig. 3 Near St#11979+30 ECD's are in place and functioning

