

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Thursday, April 18, 2019	Project Contact:	Brian Clauto
Spread: Craig County AR GI 258.02 MP 218 St#11254-11473	Spread G	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:

- Streams inspected included: S-PP4, S-PP3
- St#11517+81 water bar conveyance is eroding
- St#11511+00 two tone area is eroding and requires repair / stabilization
- St#11489 clean water diversion inlet has eroded
- St#11473 two tone area is eroding and requires repair / stabilization

Recommended Corrective Action: Maintain all controls per the approved plan and specs.

Deadline: Within 24hr notification.

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 5-6-19

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, April 18, 2019

- Fig. 1 St#11517+81 water bar conveyance is eroding



- Fig. 2 St#11511+00 two tone area is eroding and requires repair / stabilization



- Fig. 3 St#11489 clean water diversion inlet has eroded



- Fig. 4 St#11473 two tone area is eroding and requires repair / stabilization

