

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, May 28, 2019	Project Contact:	Brian Clauto
Spread: Montgomery County MP223-224 St11790-11849 MLV26 AR256.02	Spread G	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing
 Rough Grading
 Trench Excavation
 Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration
 Final Grading & Stabilization
 Other: Dormant

Yes No N/A

- | | | | | |
|---|---|---|---|---|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | □ | □ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | □ | □ |
| 3 | Areas of offsite sediment deposition were observed? | □ | ☒ | □ |

Comments:

- Stream inspected included: S-NN12, ECD's were in place at stream inspected and no impacts were observed.
- St#11790-11849 new install of permanent bars

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Matthew Grant* Date: 6-17-19

FIELD INSPECTION PHOTO LOG


Project Name: Mountain Valley Pipeline

Date: Tuesday, May 28, 2019

- Fig. 1. Near St11860+90 permanent stabilization has been applied



- Fig. 2. Near St#11857+00 new permanent water bar install



- Fig. 3 Near St#11790+28 new permanent water bar install



- Fig. 3 Active construction of permanent water bar

