

## FIELD INSPECTION

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Matthew Grant
<b>Inspection Date:</b>	Wednesday, May 8, 2019	<b>Project Contact:</b>	Brian Clauto
<b>Spread: Craig County MP217 AR258.01</b>	Spread G	<b>Weather (Wet/Dry/Rain):</b>	Dry

**STAGE OF CONSTRUCTION:** (Check all that apply)

- |  |  |  |  |
|--|--|--|--|
| <input type="checkbox"/> Clearing                          | <input type="checkbox"/> Rough Grading                 | <input type="checkbox"/> Trench Excavation         | <input type="checkbox"/> Pipe Assembly, Testing & Installation |
| <input type="checkbox"/> Backfilling and Grade Restoration | <input type="checkbox"/> Final Grading & Stabilization | <input checked="" type="checkbox"/> Other: Dormant |  |

Yes No N/A

- |   |   |   |   |   |
|---|---|---|---|---|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3 | Areas of offsite sediment deposition were observed?   | ☐ | ☒ | ☐ |

**Comments:**

- Streams inspected included: S-PP1, S-0012, S-0013. ECD's were in place at all streams inspected and no impacts were observed.

**Recommended Corrective Action:** N/A

**Deadline:**   N/A  

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:     *Matthew Grant*     Date:   6-17-19

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Wednesday, May 8, 2019

- Fig. 1 Designated stream SPP-1 ECD's are in place and functioning.



- Fig. 2 St#11478+00 two-tone areas have been blanket matted.



- Fig. 3 Above designated streams S-0012 and S-0013, ECD's in place.



- Fig. 4 Access road 258.01 controls in place and functioning.

