

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, June 18, 2019	Project Contact:	Brian Clauto
Spread: Montgomery County MP223 11788-11900 AR266.03	Spread G	Weather (Wet/Dry/Rain):	Dry
STAGE OF CONSTRUCTI	ION: (Check all that apply)		
Clearing	Rough Grading	Trench Excavation	Pipe Assembly, Testing & Installation
Backfilling and Grade	e Restoration	& Stabilization	Other: Dormant
_	_	Yes No N/A	_
	d and implemented in accordance with the nt control plan and stormwater management		
2 condition in accorda	ures properly maintained in effective oper ince with good engineering practices and, sturer specifications?		
3 Areas of offsite sedi	ment deposition were observed?		
Comments: Check dams on AR 266.03 require maintenance Access Rd gravel was offsite and was being removed at the time of the inspection. Recommended Corrective Action: Maintain all controls per the approved plan and specs			
<u>Deadline:</u> _Within 24hr notification The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.			
Inspector Signature: Date: _6-24-19			



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline Date:Tuesday, June 18, 2019

Fig. 1. Check dam on AR 266.03 requires maintenance



Fig. 2. Check dams on AR 266.03 requires maintenance



 Fig. 3. Repairs and offsite gravel removal being conducted on AR 266.03



Fig. 4.