

## FIELD INSPECTION

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Matthew Grant
<b>Inspection Date:</b>	Tuesday, July 9, 2019	<b>Project Contact:</b>	Brian Clauto
<b>Spread: Giles County</b> AR 25 MP 212 St11227 AR 28 <b>Montgomery County</b> MLV 26 MP222- 223 St11766+76-11804	<b>Spread G</b>	<b>Weather (Wet/Dry/Rain):</b>	<b>Dry</b>

**STAGE OF CONSTRUCTION:** (Check all that apply)

- Clearing                       Rough Grading                       Trench Excavation                       Pipe Assembly, Testing & Installation  
 Backfilling and Grade Restoration                       Final Grading & Stabilization                       Other: Dormant

- |   |   | Yes                                 | No                                  | N/A                      |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?   | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**Comments:**

- Designated stream inspected included: W-IJ 46 ECD controls were in place and functioning at crossing.
- St11766+76 through 11764 lacks adequate temporary stabilization
- St11764+00 ECD j hook requires maintenance
- St11783+95 erosion and inadequate stabilization near ECD sump

**Recommended Corrective Action:** Maintain all controls per the approved plan and specs

**Deadline:** Within 24hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 7/22/19

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Tuesday, July 9, 2019

- Fig. 1. Designated stream W-IJ 46 ECD controls were in place and functioning at crossing



- Fig. 2. St11766+76 through 11764 lacks adequate temporary stabilization



- Fig. 3. St11764+00 ECD j hook requires maintenance



- Fig. 4. St11783+95 erosion and inadequate stabilization near ECD sump

