

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, September 23, 2019	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Montgomery County	STA 11788+23 – 11900+00 MVP-MN-266.03	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other:

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: N/A.

Recommended Corrective Action: N/A

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.





Inspector Signature: *Marshall Willis*

Date: 09/23/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, September 23, 2019

<p>Fig. 1: STA 11798+00 – Final restoration in progress. Installation of erosion fabric. Area stabilized with seed and straw.</p> <p style="text-align: center;">📍 95°E (T) 📍 37°17'46"N, 80°21'28"W ±32.8ft ▲ 2146ft</p>  <p style="text-align: right; font-size: small;">11798 23 Sep 2019, 10:20:40</p>	<p>Fig. 2: STA 11815+00 – Controls in place. Area stabilized with seed and straw.</p> <p style="text-align: center;">📍 148°SE (T) 📍 37°17'46"N, 80°21'10"W ±32.8ft ▲ 2210ft</p>  <p style="text-align: right; font-size: small;">11815 23 Sep 2019, 10:29:07</p>
<p>Fig. 3: STA 11825+00 – Controls in place. Area stabilized with seed and straw.</p> <p style="text-align: center;">📍 179°S (T) 📍 37°17'36"N, 80°21'3"W ±16.4ft ▲ 2276ft</p>  <p style="text-align: right; font-size: small;">11825 23 Sep 2019, 10:36:10</p>	<p>Fig. 4: STA 11890+00 – Controls in place. Area stabilized with seed and straw.</p> <p style="text-align: center;">📍 291°W (T) 📍 37°17'15"N, 80°20'15"W ±16.4ft ▲ 2205ft</p>  <p style="text-align: right; font-size: small;">11890 23 Sep 2019, 12:23:23</p>