

## FIELD INSPECTION

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Tuesday, December 10, 2019	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread H: Montgomery County</b>	STA 12175+00 – 12190+85 ATWS 703 MVP-MN-274	<b>Weather (Wet/Dry/Rain):</b>	Rainy

**STAGE OF CONSTRUCTION:** (Check all that apply)

- Clearing                       Rough Grading                       Trench Excavation                       Pipe Assembly, Testing & Installation  
 Backfilling and Grade Restoration                       Final Grading & Stabilization                       Other: Dormant

- |   |   | Yes                                 | No                                  | N/A                      |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?   | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: N/A

**Recommended Corrective Action:** N/A

**Deadline:** Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 12/10/2019

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Tuesday, December 10, 2019

Fig. 1: **MVP-MN-273** – Controls in place and properly functioning along MVP-MN-273.

☉ 90°E (T) ● 37°15'6"N, 80°15'37"W ±16.4ft ▲ 1281ft



Fig. 2: **STA 12178+00** – Controls in place and functioning properly. Area stabilized with hydro-mulch and erosion fabric.

☉ 314°NW (T) ● 37°15'11"N, 80°15'45"W ±16.4ft ▲ 1373ft



Fig. 3: **STA 12183+33** – Controls in place and functioning. Area stabilized with seed, straw and hydro-mulch.

☉ 81°E (T) ● 37°14'25"N, 80°15'35"W ±6368.4ft ▲ 1299ft



Fig. 4: **Bradshaw Road** – Controls in place and properly functioning along Bradshaw Road.

☉ 156°SE (T) ● 37°15'7"N, 80°15'34"W ±16.4ft ▲ 1286ft

