

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, December 27, 2019	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Franklin County	STA 13316+13 – 13415+51 ATWS 1352	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-IJ3, W-IJ2-PSS, W-IJ1, S-IJ2, S-IJ1, S-RR11, S-RR09, S-RR08, S-GH9, S-GH11, S-GH14 and S-GH15.

- STA 13383+00: P1 maintenance needed.

Recommended Corrective Action: Maintain and install all controls per the approved plans and PSS&S.

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 12/27/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, December 27, 2019

Fig. 1: **STA 13403+00** – Controls in place and properly functioning. Area stabilized with erosion matting.

☉ 97°E (T) ● 37°5'36"N, 80°1'45"W ±32.8ft ▲ 2317ft



Fig. 2: **STA 13383+00** – P1 maintenance needed.

☉ 58°NE (T) ● 37°5'56"N, 80°2'0"W ±16.4ft ▲ 1689ft



Fig. 3: **STA 13371+00** – Controls in place and functioning. Area stabilized with erosion matting.

☉ 275°W (T) ● 37°6'5"N, 80°2'8"W ±32.8ft ▲ 1794ft



Fig. 4: **Stream S-GH15**– Controls in place and properly functioning along stream S-GH15. Area stabilized with erosion matting.

☉ 86°E (T) ● 37°6'21"N, 80°3'1"W ±164.1ft ▲ 1488ft

