

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Thursday, February 27, 2020	Project Contact:	Brian Clauto,
Spread H: Franklin	MP 251-252 MP253.8- 253.9 ATWS 1412, 1055 AR FR 293.01	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| <input type="checkbox"/> Tree Felling | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading | <input type="checkbox"/> Trenching | <input type="checkbox"/> Stringing/Welding |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Grading | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

- Comments: Inspected the following resources: S-II4, S-GH7, S-IJ1, W-IJ2
- ECD's were in place at crossings and appeared to be functioning.

Routine Maintenance: (72-Hour Deadline from Notification)
- N/A

Ineffective Controls: (24-Hour Deadline from Notification)
- N/A

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.


Inspector Signature: _____  _____

Date: Thursday, February 27, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, February 27, 2020

<p>Figure 1: Designated crossing S-II4, ECD's are in place.</p> <div style="text-align: center;"> <p>East Elevation</p> <p>☉ 265°W (T) ☉ 37°6'56"N, 80°3'35"W ±16ft ▲ 1442ft</p>  </div>	<p>Figure 2: Designated crossing S-GH7, ECD's are in place.</p> <div style="text-align: center;"> <p>South East Elevation</p> <p>☉ 326°NW (T) ☉ 37°6'23"N, 80°3'14"W ±16ft ▲ 1349ft</p>  </div>
<p>Figure 3: Designated crossings S-IJ1 & W-IJ2, ECD's are in place.</p> <div style="text-align: center;"> <p>South East Elevation</p> <p>☉ 314°NW (T) ☉ 37°5'32"N, 80°1'37"W ±1620ft ▲ 1424ft</p>  </div>	<p>Figure 4: Near MP25.3 ECD's are in place and the area is well stabilized.</p> <div style="text-align: center;"> <p>South Elevation</p> <p>☉ 369°N (T) ☉ 37°6'22"N, 80°3'16"W ±16421ft ▲ 1582ft</p>  </div>