

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, February 5, 2020	Project Contact:	Brian Clauto
Spread H: Montgomery	AR-MN 276.03 MLV AR- 27 ATWS 724	Weather:	Rainy

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| <input type="checkbox"/> Tree Felling | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading | <input type="checkbox"/> Trenching | <input type="checkbox"/> Stringing/Welding |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Grading | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-NN19, S-0016

- Controls inspected were in place and appeared to be functioning.


Routine Maintenance: (72-Hour Deadline from Notification)
- N/A

Ineffective Controls: (24-Hour Deadline from Notification)
- N/A

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.




Inspector Signature: _____  _____

Date: Wednesday, February 5, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, February 5, 2020

<p>Figure 1: Near MP 232.4 areas has been stabilized with blanket matting.</p> <p style="text-align: center;">North West Elevation</p> <p style="text-align: center;">☉ 150°SE (T) ● 37°15'21"N, 80°13'35"W ±16ft ▲ 2585ft</p> 	<p>Figure 2: Near MP 234 area remains stabilized with ECD blanket matting.</p> <p style="text-align: center;">North West Elevation</p> <p style="text-align: center;">☉ 137°SE (T) ● 37°14'46"N, 80°12'38"W ±32ft ▲ 1426ft</p> 
<p>Figure 3: Near MP 233.4 are remains stabilized with ECD blanket matting.</p> <p style="text-align: center;">South Elevation</p> <p style="text-align: center;">☉ 424°N (T) ● 37°15'10"N, 80°12'53"W ±32ft ▲ 1740ft</p> 	<p>Figure 4: Near MLV AR 27 area is stabilized and ECD's are in place.</p> <p style="text-align: center;">South Elevation</p> <p style="text-align: center;">☉ 395°N (T) ● 37°14'23"N, 80°11'57"W ±16ft ▲ 1391ft</p> 