

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, March 19, 2019	Project Contact:	Brian Clauto
Spread H: Montgomery County Roanoke County	STA 12054+00 – 12140+00 STA 12451+61 – 12460+00	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: Dormant

- | | | Yes | No | N/A |
|---|---|--------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-MM15, S-MM14, S-MM13, S-MM11, S-F15, W-F9-PFO, S-F16, S-C33, S-C36 and S-C29.

- STA 12065+00: P1 undermined at several locations along perimeter.
- STA 12092+80: CWD does not have inlet protection.
- STA 12098+44: Repair CFS at CIS S-MM13.
- STA 12100+00: Perimeter CWD berm failing.

Recommended Corrective Action: Maintain and install all controls per the approved plan and specs.

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 03/19/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, March 19, 2019

Fig. 1: STA 12066+00 – Area adequately stabilized. Controls in place.



Fig. 2: STA 12065+00 – P1 undermined in several locations.



Fig. 3: STA 12054+00 – Area adequately stabilized. Controls in place.




Fig. 4: STA 12084+00 – Area adequately stabilized. Controls in place.



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, March 19, 2019

Fig. 5: STA 12092+80 – Inlet protection needed at CWD.



Fig. 6: STA 12098+44 – Repair CFS at S-MM13.



Fig. 7: STA 12100+00 – Perimeter CWD berm failing.



Fig. 8: STA 12135+00 – Area adequately stabilized. Controls in place.

