

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, March 22, 2019	Project Contact:	Brian Clauto
Spread H: Montgomery County	STA 12144+47 – 12188+34 STA 11993+00 – 12015+84	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-C24, S-C25, S-G38, S-G36 and W-NN6.

- STA 12156+86: CWD does not have inlet protection.
- STA 12168+75: Re-stake geo-fabric.

Recommended Corrective Action: Maintain and install all controls per the approved plan and specs.

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 03/22/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, March 22, 2019

Fig. 1: STA 12178+00 – Area adequately stabilized. Controls in place.



Fig. 2: STA 12167+34 – Area adequately stabilized. Controls in place.



Fig. 3: STA 12161+00 – Area adequately stabilized. Controls in place.



Fig. 4: STA 12156+86 – CWD needs inlet protection.



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, March 22, 2019

Fig. 5: STA 12168+75 – Re-stake fabric.



Fig. 6: STA 12073+57 – Area adequately stabilized. Controls in place.



Fig. 7: STA 12006+00 – Area adequately stabilized. Controls in place.



Fig. 8: STA 12008+53 – Area adequately stabilized. Controls in place.

