

FIELD INSPECTION

| | | | |
|--------------------------------------|---|--------------------------------|-----------------|
| Project Name: | Mountain Valley Pipeline | Inspector: | Marshall Willis |
| Inspection Date: | Wednesday, April 24, 2019 | Project Contact: | Brian Clauto |
| Spread H: Franklin County | STA 13035+59 – 13115+97 MVP-FR-289/291 | Weather (Wet/Dry/Rain): | Dry |

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-H1, S-G26 and S-G27.

Recommended Corrective Action: N/A

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 04/24/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, April 24, 2019

Fig. 1: **STA 13120** – Controls in place. Area stabilized with curlex fabric.



Fig. 2: **STA 13108** – Controls in place. Area stabilized with curlex fabric.



Fig. 3: **STA 13097+48** – Controls in place. Area stabilized with curlex fabric.



Fig. 4: **STA 13086** – Controls in place. Area stabilized with curlex fabric.



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, April 24, 2019

Fig. 5: **STA 13079** – Controls in place. Area stabilized with curlex fabric.

☉ 269°W (T) ● 37°7'35"N, 80°6'22"W ±32.8ft ▲ 2835ft



Fig. 6: **STA 13072** – Controls in place. Area stabilized with curlex fabric.

☉ 60°NE (T) ● 37°7'33"N, 80°6'29"W ±16.4ft ▲ 2796ft



Fig. 7: **STA 13053** – Controls in place. Area stabilized with Earth Guard and straw.

☉ 264°W (T) ● 37°7'42"N, 80°6'50"W ±16.4ft ▲ 2698ft



Fig. 8: **S-H1** – Controls in place. Area stabilized with curlex fabric.

☉ 296°NW (T) ● 37°7'39"N, 80°7'0"W ±16.4ft ▲ 2654ft

