

## FIELD INSPECTION

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Wednesday, May 22, 2019	<b>Project Contact:</b>	Brian Clauto
<b>Spread H: Franklin County</b>	STA 13197+35 – 13318+21	<b>Weather (Wet/Dry/Rain):</b>	Dry

**STAGE OF CONSTRUCTION:** (Check all that apply)

- Clearing                       Rough Grading                       Trench Excavation                       Pipe Assembly, Testing & Installation  
 Backfilling and Grade Restoration                       Final Grading & Stabilization                       Other: Dormant

- |   |   | Yes                                 | No                                  | N/A                      |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?   | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-II4 and S-GH7.

**Recommended Corrective Action:** N/A

**Deadline:** Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 05/22/2019

# FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Wednesday, May 22, 2019

**Fig. 1: STA 13211+00** – Controls in place. Area stabilized with erosion fabric/Earth Guard.



**Fig. 2: STA 13221+00** – Controls in place. Area stabilized with erosion fabric/Earth Guard.



**Fig. 3: STA 13236+00** – Controls in place. Area stabilized with erosion fabric/Earth Guard.



**Fig. 4: STA 13245+00** – Controls in place. Area stabilized with erosion fabric/Earth Guard.





# FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Wednesday, May 22, 2019

**Fig. 5: STA 13254+00** – Controls in place. Area stabilized with erosion fabric/Earth Guard.



**Fig. 6: STA 13289+00** – Controls in place. Area stabilized with erosion fabric/Earth Guard.



**Fig. 7: STA 13303+00** – Controls in place. Area stabilized with erosion fabric/Earth Guard.



**Fig. 8: Stream S-GH7** – Controls in place.

