

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, May 27, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Franklin County	STA 13306+16 – 13316+00 STA 13411+83 – 13415+51 ATWS 1412/1352	Weather:	Rainy

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-GH7, S-IJ3, W-IJ2-PSS, W-IJ1, S-IJ2 and S-IJ1.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Wednesday, May 27, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, May 27, 2020

Figure 1: STA 11306+50 – Controls in place and functioning properly at the Wades Gap crossing.

☉ 124°SE (T) ● 37°6'23"N, 80°3'6"W ±328ft ▲ 1310ft



Wades Gap

Figure 2: Stream S-GH7 – Controls in place and functioning properly around S-GH7 crossing. Area stabilized.

☉ 283°W (T) ● 37°4'30"N, 80°3'14"W ±14098ft ▲ 1426ft



A-GH7

Figure 3: STA 11306+50 – Controls in place and functioning properly at the Cahas Road crossing.

☉ 317°NW (T) ● 37°5'34"N, 80°1'31"W ±16ft ▲ 1492ft



Cahas

Figure 4: Stream S-IJ1 – Controls in place and functioning properly at stream S-IJ1 crossing. Area stabilized.

☉ 296°NW (T) ● 37°5'34"N, 80°1'39"W ±16ft ▲ 1456ft



S-IJ1