

FIELD INSPECTION REPORT

| | | | |
|--|---|-------------------------|-----------------------------|
| Project Name: | Mountain Valley Pipeline | Inspector: | Marshall Willis |
| Inspection Date: | Tuesday, June 2, 2020 | Project Contact: | Brian Clauto, Cory Chalmers |
| Spread H: Montgomery County | STA 12072+50 – 12188+34 MVP-MN-270/271/273/274 ATWS 1163/1162/701/1167/1168 | Weather: | Dry |

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-MM15, S-MM14, S-MM13, S-MM11, S-F15, W-F9-PFO, W-C12, S-C33, S-C36, W-C11, S-MM31, S-C29, W-C6, W-C5, S-C25 and S-C24.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Tuesday, June 2, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, June 2, 2020

Figure 1: STA 12072+00 – Controls in place and functioning properly. Area stabilized.

☉ 332°NW (T) ● 37°13'57"N, 80°15'41"W ±6391ft ▲ 1349ft



Figure 2: STA 12085+00 – Controls in place and functioning properly. Area stabilized.

☉ 108°E (T) ● 37°14'10"N, 80°15'43"W ±6391ft ▲ 1765ft



Figure 3: STA 12120+00 – Controls in place and functioning properly. Area stabilized.

☉ 97°E (T) ● 37°14'8"N, 80°15'40"W ±6391ft ▲ 1493ft



Figure 4: STA 12155+00 – Controls in place and functioning properly. Area stabilized.

☉ 55°NE (T) ● 37°14'7"N, 80°15'40"W ±6391ft ▲ 1437ft

