

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Thursday, July 25, 2019	Project Contact:	Brian Clauto
Spread: Franklin Co. MP251 St13260	Spread H	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: Bore site

- | | | Yes | No | N/A |
|---|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:

- Inspected designated stream included: S-II4
- During the inspection the dewatering structure and ECD's were in place and functioning at the bore pit site.

Recommend Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 8-5-19

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, July 25, 2019

<p>▪ Fig. 1 Flanders Rd bore pit site.</p> <div style="border: 1px solid black; padding: 5px;"> <p style="text-align: center;">East Elevation</p> <p style="text-align: center;">☉ 275°W (T) ☉ 37°6'56"N, 80°3'35"W ±16.4ft ▲ 1471ft</p>  </div>	<p>▪ Fig. 2 Dewatering structure at the Flanders bore pit site was functioning at the time of the inspection.</p> <div style="border: 1px solid black; padding: 5px;"> <p style="text-align: center;">North East Elevation</p> <p style="text-align: center;">☉ 238°SW (T) ☉ 37°6'54"N, 80°3'35"W ±16.4ft ▲ 1419ft</p>  </div>
<p>▪ Fig. 3. Flanders Rd bore pit site.</p> <div style="border: 1px solid black; padding: 5px;"> <p style="text-align: center;">North East Elevation</p> <p style="text-align: center;">☉ 239°SW (T) ☉ 37°6'56"N, 80°3'35"W ±16.4ft ▲ 1444ft</p>  </div>	