

FIELD INSPECTION REPORT

| | | | |
|--|--|-------------------------|-----------------------------|
| Project Name: | Mountain Valley Pipeline | Inspector: | Marshall Willis |
| Inspection Date: | Wednesday, August 12, 2020 | Project Contact: | Brian Clauto, Cory Chalmers |
| Spread H: Montgomery County | STA 12033+34 – 12072+00 MVP-MN-270/268 ATWS 1162/1163/1161 | Weather: | Dry |

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-PP23, W-PP8, S-G40, S-G39 and S-G36.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Wednesday, August 12, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, August 12, 2020

Figure 1: STA 12072+00 – Controls in place and functioning properly.

☉ 8°N (T) ● 37°15'30"N, 80°17'52"W ±32ft ▲ 1847ft



Figure 2: STA 12051+00 – Controls in place and functioning properly.

☉ 325°NW (T) ● 37°15'42"N, 80°18'8"W ±98ft ▲ 2319ft



Figure 3: STA 12040+00 – Controls in place and functioning properly. Area stabilized.

☉ 315°NW (T) ● 37°16'31"N, 80°18'30"W ±6479ft ▲ 2099ft



Figure 4: Stream S-G40 – Controls in place and functioning properly around S-G40 crossing.

☉ 137°SE (T) ● 37°15'53"N, 80°18'27"W ±32ft ▲ 1765ft

