

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, August 13, 2019	Project Contact:	Cory Chalmers
Spread: Montgomery County MP236 St12470-12482+67	Spread H	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:

- Inspected designated wetland included: WKL 58, ECD's were in place and functioning.
- ECD's in this section of ROW are in place and functioning, stabilization has been applied as well.

Recommend Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 8-19-19

FIELD INSPECTION PHOTO LOG


Project Name: Mountain Valley Pipeline

Date: Tuesday, August 13, 2019

- Fig. 1 Designated wetland WKL58, ECD's are in place and functioning.



- Fig. 2 Near St12470+00 stabilization has been applied.



- Fig. 3. Near St12181+00 ECD's are in place and stabilization has been applied.



- Fig. 4. Near St12482+67 stabilization has been applied.

