

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, August 15, 2019	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12482+67– 12544+06	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: Stop Work Instruction Area

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Re-inspection of the Stop Work Instruction (SWI) area (STA 12482+67 – 12544+06) as requested by MVP staff on 8/15. Previously identified corrective action items identified on 8/14 inspection have been addressed at this time.

Recommended Corrective Action: N/A

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 08/15/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, August 15, 2019

Fig. 1: **STA 12533+62** – Controls in place. Slope drains used to convey discharge down fill slopes. Stockpiles stabilized with straw and seed. Fill slopes stabilized with erosion blanket.

☉ 137°SE (T) ● 37°12'44"N, 80°11'46"W ±32.8ft ▲ 1637ft



12533+62
15 Aug 2019, 11:52:56

Fig. 2: **STA 12522+800** – Controls in place. Waterbars extend full length of ROW and connected to end-treatment CFS and sumps. Stockpiles stabilized with straw and millet.

☉ 36°NE (T) ● 37°12'55"N, 80°11'50"W ±164.1ft ▲ 1743ft



12522+00
15 Aug 2019, 12:13:24

Fig. 3: **STA 12515+30** – Controls in place. Berms stabilized with straw and millet. Waterbars installed full length of ROW and connected to sumps and end-treatments.

☉ 173°S (T) ● 37°12'59"N, 80°11'51"W ±32.8ft ▲ 1739ft



15 Aug 2019, 12:25:52

Fig. 4: **STA 12504+00** – Controls in place. Sideboards for CWD crossing installed. Area stabilized with erosion matting and millet.

☉ 337°NW (T) ● 37°13'4"N, 80°12'1"W ±3438.5ft ▲ 1767ft



12504
15 Aug 2019, 12:52:01