

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, August 5, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12445+86 – 12485+00 ATWS 645/1566 MVP-MLV-AR-28	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-CD12b and W-KL58.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Wednesday, August 5, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, August 5, 2020

Figure 1: STA 12483+00 – Controls in place and functioning properly. Area stabilized with straw and erosion matting.

☉ 155°SE (T) ● 37°13'24"N, 80°12'7"W ±16ft ▲ 1544ft



12583

Figure 2: STA 12487+00 – Controls in place and functioning properly. Area stabilized with straw and erosion matting.

☉ 11°N (T) ● 37°13'54"N, 80°12'7"W ±213ft ▲ 1559ft



12487

Figure 3: STA 12477+00 – Controls in place and functioning properly. Area stabilized with straw and erosion matting.

☉ 0°N (T) ● 37°13'54"N, 80°12'7"W ±213ft ▲ 1243ft



12477

Figure 4: STA 12457+00 – Controls in place and functioning properly.

☉ 73°E (T) ● 37°13'48"N, 80°12'0"W ±164ft ▲ 1237ft



12457