

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, January 2, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13644+82 – 13748+30 ATWS 1067/1362/566	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-GH4, S-GH3, S-GH2, S-E29, S-E28, W-E7, W-E8 and S-EF4.

Recommended Corrective Action: N/A

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 01/02/2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, January 2, 2020

Fig. 1: **STA 13644+82** – Leaning Oak Road Crossing. Controls in place and functioning properly.

☉ 125°SE (T) ● 37°5'50"N, 79°56'25"W ±10558.3ft ▲ 1201ft



Fig. 2: **STA 13662+00** – Controls in place and functioning properly. Area stabilized with Flexterra.

☉ 100°E (T) ● 37°5'25"N, 79°57'17"W ±32.8ft ▲ 1208ft



Fig. 3: **STA 13727+50** – Controls in place around Stream S-EF4 crossing. Area stabilized.

☉ 94°E (T) ● 37°4'45"N, 79°56'31"W ±16.4ft ▲ 1135ft



Fig. 4: **STA 13738+00** – Controls in place and functioning properly. Area stabilized with Flexterra.

☉ 205°SW (T) ● 37°4'37"N, 79°56'22"W ±98.4ft ▲ 1163ft

