

## FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, January 3, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13850+00 – 13958+31 ATWS 697/698A/1299A MVP-FR-303.01/305	Weather (Wet/Dry/Rain):	Rainy

**STAGE OF CONSTRUCTION:** (Check all that apply)

- Clearing                       Rough Grading                       Trench Excavation                       Pipe Assembly, Testing & Installation  
 Backfilling and Grade Restoration                       Final Grading & Stabilization                       Other: Dormant

- |   |   | Yes                                 | No                                  | N/A                      |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?   | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**Comments:** Inspected the following resources: S-C17, S-CD6, W-CD6, W-CD5, S-II2, S-CD1 and W-CD1.

- STA 13851+00: SSF maintenance needed.

**Recommended Corrective Action:** Maintain and install all controls per the approved plans and PSS&S.

**Deadline:** Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 01/03/2020

# FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Friday, January 3, 2020

**Fig. 1: STA 13853+00** – Controls in place and functioning properly. Area stabilized.

☉ 17°N (T) ● 37°3'26"N, 79°55'56"W ±7438.0ft ▲ 1118ft



**Fig. 2: STA 13851+00** – SSF maintenance needed.

☉ 64°NE (T) ● 37°3'32"N, 79°55'15"W ±32.8ft ▲ 1104ft



**Fig. 3: Wetland W-CD5** – Controls in place around wetland crossing. Area stabilized.

☉ 175°S (T) ● 37°3'19"N, 79°54'38"W ±164.1ft ▲ 1021ft



**Fig. 4: STA 13906+50** – Controls in place and functioning properly. Area stabilized.

☉ 166°S (T) ● 37°3'4"N, 79°54'37"W ±16.4ft ▲ 1064ft

