

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, October 2, 2019	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	MVP-FR-303.01/305 STA 13852+46 – 13875+73 STA 13892+45 – 13916+12 STA 13939+50 – 13930+00	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-II2, S-C17, S-CD6, W-CD8 and S-GH7.

MVP-FR-303.01: Remove/properly dispose of trash.
MVP-FR-303.01: Properly contain opened fertilizer per SWPPP. Clean up spill.

Recommended Corrective Action: Maintain and install all controls per the approved plans and PSS&S.

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 10/02/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, October 2, 2019

Fig. 1: **STA 13894+12** – Controls in place in place. Area stabilized with straw and seed.



Fig. 2: **MVP-FR-303.01** – Clean up and properly dispose of trash debris.




Fig. 3: **MVP-FR-303.01** – Clean up and properly contain opened fertilizer per SWPPP.



Fig. 4: **Stream S-GH7** – Controls in place. Sideboards and geo-underlayment in place and functioning properly.

