

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Friday, February 14, 2020	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread I: Franklin County</b>	STA 14272+62 – 14333+27 ATWS MVP-FR-313 ATWS 353/354	<b>Weather:</b>	Wet

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- Tree Felling     
  Clearing/Grubbing     
  Grading     
  Trenching     
  Stringing/Welding  
 Lowering/Backfilling     
  Final Restoration     
  Temp. Stabilization     
  Perm. Stabilization     
 Dormant

- |    |   | Yes                                 | No                                  | N/A                      |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**Comments:** Inspected the following resources: S-F9B, S-F9A, S-GG4 and S-F10.

**Ineffective Controls:** (24-Hour Deadline from Notification)

- STA 14290+60: P1 undermined from offsite run-on. Repair needed.
- STA 14320+25: Repair CWD plunge pool berm. Onsite stormwater discharge entering plunge pool.
- STA 14322+00: CFS undermined. Repair needed.

**Routine Maintenance:** (72-Hour Deadline from Notification)

- STA 14311+00 to 14314+00: Re-stabilize ROW.
- STA 14320+25: Re-stabilize ROW.
- STA 14322+00: Re-stabilize ROW.

**Recommended Corrective Action:** Maintain and install all controls per the approved PSS&S.

**Deadline:** Various - See Comments

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** Marshall Willis

**Date:** Friday, February 14, 2020

# FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Friday, February 14, 2020

**Figure 1: STA 14290+60** – P1 undermined from offsite run-on. Repair needed.



**Figure 2: STA 14311+00 to 14314+00** – Re-stabilization needed.



**Figure 3: STA 14320+25** – Plunge pool diversion berm repair needed.



**Figure 4: STA 14320+25** – Re-stabilization needed.



# FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Friday, February 14, 2020

Figure 5: STA 14322+00 – CFS undermined. Repair needed.



Figure 6: STA 14322+00 – Re-stabilization needed.

