

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, February 19, 2019	Project Contact:	Brian Clauto
Spread I: Franklin County	STA 14062+17 – 14042+83 STA 14272+24 – 14274+00 STA 14129+00 – 14171+75	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other:

- | | | Yes | No | N/A |
|---|---|--------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:

- Streams / wetlands inspected included: S-YZ4, S-YZ5, S-C8 and S-KL51.
- Waterbar does not have positive drainage at STA 14049+30.
- Further stabilization needed at STA 14272+24. Rill erosion evident.
- P1 and CFS need maintenance at STA 14273+25.
- SSF needs repair in ATWS 1478.
- Sump full at GAS S-C8.
- CFS needs maintenance at STA 14148+57.
- Stabilization needed adjacent to S-KL51.

Recommended Corrective Action: Maintain and install all controls per the approved plan and specs.

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 02/19/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, February 19, 2019

Fig. 1: STA 14049+30 – Waterbar does not have positive drainage.



Fig. 2: STA 14272+24 – Stabilization needed.




Fig. 3: STA 14273+25 – Maintain P1.



Fig. 4: STA 14273+25 – Clean out CFS.



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, February 19, 2019

Fig. 5: ATWS 1478 – Repair SSF.



Fig. 6: GAS S-C8 – Sump full.



Fig. 7: STA 14148+57 – Maintain CFS.



Fig. 8: CIS S-KL51 – Stabilize areas adjacent to resource.

