

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Thursday, February 6, 2020	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread I: Franklin County</b>	STA 13996+56 – 14000+00 STA 14062+51 – 14066+77 STA 14171+36 – 14176+09 STA 14222+09 – 14224+45 STA 14233+12 – 14240+00 MVP-FR-306.02/311/300/302 MVP-MLV-AR-32	<b>Weather:</b>	Rainy

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- Tree Felling     
  Clearing/Grubbing     
  Grading     
  Trenching     
  Stringing/Welding  
 Lowering/Backfilling     
  Final Restoration     
  Temp. Stabilization     
  Perm. Stabilization     
 Dormant

- |                                                                                                                                                                                    | Yes                                 | No                                  | N/A                      |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?                                                                                                                                  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**Comments:** Inspected the following resources: S-KL36, S-KL52, S-C20 and S-C19.

- Turbid stormwater run-on was documented entering the ROW at approx. STA 13996+00. Source of turbid discharge appears to be a logging operation located on private property above the ROW. Turbid water was treated by MVP ESCs prior to entering stream S-KL36. See Figures 1 and 2.

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** 

**Date:** Thursday, February 6, 2020

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Thursday, February 6, 2020

**Figure 1: STA 13996+50** – Turbid stormwater discharge from offsite and upslope logging operation. Run-on treated by MVP ESC prior to entering stream S-KL36.

☉ 213°SW (T) ● 37°3'12"N, 79°53'4"W ±16.4ft ▲ 1004ft



**Figure 2: STA 13996+50** – Turbid stormwater discharge from offsite and upslope logging operation. Run-on treated by MVP ESC prior to entering stream S-KL36.

☉ 47°NE (T) ● 37°3'11"N, 79°53'5"W ±32.8ft ▲ 1000ft



**Figure 3: STA 14064+50** – Controls in place and functioning properly.

☉ 0°N (T) ● 37°3'54"N, 79°52'28"W ±98.4ft ▲ 1176ft



**Figure 4: STA 14233+50** – Maggodee Creek crossing looking W. Controls in place and functioning properly.

☉ 250°W (T) ● 37°3'18"N, 79°49'47"W ±32.8ft ▲ 893ft

