

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, April 18, 2019	Project Contact:	Brian Clauto
Spread I: Franklin County	STA 14712+33 – STA 14730+00 STA 13541+73, STA 13416+00 STA 14549+84, STA 14532+00	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-G18, S-W-H11, S-H30, W-A8, S-A18, S-A19 and S-II9.

STA 13416+00: Sediment off ROW potentially impacting W-IJ3.
 STA 14712+35: Maintenance required on RCEs.
 STA 14719+37: Maintenance required on RCEs.
 STA 14719+37: Adequately stabilize ATWS 1279.
 STA 14722+11: Sump and CFS clean out in ATWS 1279.
 STA 14727+07: CFS and end treatment repair CIS of S-A19.
 STA 14727+00 – 14728+00: Stabilize stockpiles around S-A19/A20.

Recommended Corrective Action: Maintain and install all controls per the approved plan and specs.

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 04/18/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, April 18, 2019

<p>Fig. 1: STA 14712+35 – Repair/maintain RCEs.</p>  <p style="font-size: small; text-align: center;"> 248°W (T) ● 36°59'17"N, 79°42'14"W ±16.4ft ▲ 936ft RCE 14712+35 18 Apr 2019 11:06:52 </p>	<p>Fig. 2: STA 14719+37 – Repair/maintain RCEs.</p>  <p style="font-size: small; text-align: center;"> 138°SE (T) ● 36°59'16"N, 79°42'6"W ±16.4ft ▲ 914ft RCE 14719+37 18 Apr 2019 11:15:22 </p>
<p>Fig. 3: STA 14719+37 – Adequately stabilize ATWS 1279.</p>  <p style="font-size: small; text-align: center;"> 56°NE (T) ● 36°59'16"N, 79°42'5"W ±16.4ft ▲ 918ft Stabilize ATWS 1279 18 Apr 2019 11:19:17 </p>	<p>Fig. 4: STA 14722+11 – Clean out sump in ATWS 1279.</p>  <p style="font-size: small; text-align: center;"> 18°N (T) ● 36°59'16"N, 79°42'3"W ±16.4ft ▲ 896ft Sump ATWS 1279 18 Apr 2019 11:20:08 </p>

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, April 18, 2019



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, April 18, 2019

Fig. 9: STA 13416+00 – Sediment off ROW. Potential impact to W-IJ3.



Fig. 10: STA 13541+00: Controls in place.in place.



Fig. 11: STA 13542+18: Controls in place.



Fig. 12: S-II9 – Controls in place. Banks Stabilized.

