

## FIELD INSPECTION

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Tuesday, April 30, 2019	<b>Project Contact:</b>	Brian Clauto
<b>Spread I: Franklin County</b>	STA 13690+91 – 13748+30 STA 13631+27 – 13644+52	<b>Weather (Wet/Dry/Rain):</b>	Dry

**STAGE OF CONSTRUCTION:** (Check all that apply)

- Clearing                       Rough Grading                       Trench Excavation                       Pipe Assembly, Testing & Installation  
 Backfilling and Grade Restoration                       Final Grading & Stabilization                       Other: Dormant

- |   |   | Yes                                 | No                                  | N/A                      |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?   | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-EF4, and S-E28.

**Recommended Corrective Action:** N/A

**Deadline:** Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 04/30/2019

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Tuesday, April 30, 2019

<p>Fig. 1: <b>STA 13745+00</b> – Area stabilized. Controls in place.</p> <div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> <p>☉ 241°SW (T) ● 37°4'31"N, 79°56'24"W ±16.4ft ▲ 1228ft</p> </div>  <div style="text-align: right; font-size: small; margin-top: 5px;"> <p>13745+00 30 Apr 2019, 11:15:09</p> </div>	<p>Fig. 2: <b>STA 13735+00</b> – Controls in place. Area stabilized with Earth Guard.</p> <div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> <p>☉ 161°S (T) ● 37°4'41"N, 79°56'23"W ±16.4ft ▲ 1226ft</p> </div>  <div style="text-align: right; font-size: small; margin-top: 5px;"> <p>13735+00 30 Apr 2019, 11:20:31</p> </div>
<p>Fig. 3: <b>STA 13720+00</b> – Controls in place. Area stabilized.</p> <div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> <p>☉ 4°N (T) ● 37°4'43"N, 79°56'30"W ±16.4ft ▲ 1144ft</p> </div>  <div style="text-align: right; font-size: small; margin-top: 5px;"> <p>13720+00 30 Apr 2019, 11:26:18</p> </div>	<p>Fig. 4: <b>Stream S-EF4</b> – Controls in place.</p> <div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> <p>☉ 215°SW (T) ● 37°4'44"N, 79°56'30"W ±16.4ft ▲ 1123ft</p> </div>  <div style="text-align: right; font-size: small; margin-top: 5px;"> <p>S-EF4 30 Apr 2019, 11:28:28</p> </div>

# FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Tuesday, April 30, 2019

**Fig. 5: STA 13721+00** – Area stabilized. Controls in place.



**Fig. 6: STA 13719+00** – Area stabilized. Controls in place.



**Fig. 7: STA 13712+50** – Area stabilized with straw and curlex.



**Fig. 8: STA 13712+50** – Area stabilized with straw and curlex.

