

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, May 14, 2019	Project Contact:	Brian Clauto
Spread I: Pittsylvania County	STA 15584+23 – 15647+03	Weather (Wet/Dry/Rain):	Wet

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: W-MM9, S-CC1, S-CC3, W-MM8-PFO, W-MM8-PEM, S-P5 and S-IJ35-EPH.

- STA 15594+04 – Waterbar maintenance required.
- STA 15614+00 – Additional stabilization needed.
- STA 15632+00 – CFS undermined.

Recommended Corrective Action: Maintain and install all controls per the approved plan and specs.

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 05/14/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, May 14, 2019

Fig. 1: STA 15586+00 – Controls in place. Area adequately stabilized with straw and Earth Guard.



Fig. 2: STA 15594+04 – Waterbar maintenance required.



Fig. 3: STA 15614+00 – Inadequate stabilization.



Fig. 4: STA 15623+00 – CFS undermined.



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, May 14, 2019

Fig. 5: **STA 15640+00** – Controls in place. Area adequately stabilized with straw and Earth Guard.



Fig. 6: **Stream S-CC1** – Controls in place.



Fig. 7: **Stream S-CC3** – Controls in place.



Fig. 8: **STA 15615+12** – Controls in place. Area adequately stabilized with straw and Earth Guard.

