

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, May 18, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13415+50 – 13441+50 MVP-FR-293.02 ATWS 1351/1342/1343	Weather:	Rainy

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-IJ4.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Monday, May 18, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, May 18, 2020

Figure 1: STA 13416+00 – Controls in place and functioning properly.

☉ 120°SE (T) ● 37°3'30"N, 80°3'8"W ±12395ft ▲ 1278ft



Figure 2: STA 13423+00 – Controls in place and functioning properly.

☉ 100°E (T) ● 37°5'29"N, 80°1'30"W ±16ft ▲ 1465ft



Figure 3: STA 13436+00 – Controls in place and functioning properly.

☉ 272°W (T) ● 37°5'25"N, 80°1'14"W ±16ft ▲ 1699ft



Figure 4: STA 13440+00 – Controls in place and functioning properly.

☉ 132°SE (T) ● 37°5'25"N, 80°1'10"W ±32ft ▲ 1651ft

