

FIELD INSPECTION

| | | | |
|--|--------------------------|--------------------------------|---------------|
| Project Name: | Mountain Valley Pipeline | Inspector: | Matthew Grant |
| Inspection Date: | Tuesday, May 7, 2019 | Project Contact: | Brian Clauto |
| Spread: Pittsylvania County MP285.8-284.9 | Spread I | Weather (Wet/Dry/Rain): | Dry |

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |


Comments:

- Streams / wetlands inspected included: S-Q15, S-G8, W-B4-PS5, S-G9, S-G11, GAS-D1-EPH, W-D3, S-D2. ECD's were in place at all inspected streams and no impacts were observed.
- GAS-D1-EPH has had bank repair conducted per previous inspection dated 3/6/19.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:  Date: 6-17-19

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, May 7, 2019

- Fig. 1 GAS-D1-EPH has had bank repair conducted per previous inspection dated 3/6/19.



- Fig. 2 GAS-D1-EPH has had bank repair conducted per previous inspection dated 3/6/19.



- Fig. 3 Above designated stream S-D2 and wetland W-D3, ECD's are in place and functioning.

