

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, June 1, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13437+75 – 13541+66 MVP-FR-293.02 ATWS 1414/1253/1252/1066	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-IJ8, W-IJ6, S-IJ10, S-KL1, S-KL2, S-II8, S-II7 and W-II8.

Routine Maintenance: (*72-Hour Deadline from Notification*)
 - STA 13495+00: Repair re-stabilize erosion.

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Monday, June 1, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, June 1, 2020

Figure 1: STA 13438+00 – Controls in place and functioning properly. Area stabilized.

☉ 139°SE (T) ● 37°3'47"N, 79°58'31"W ±13019ft ▲ 1723ft



13438

Figure 2: STA 13487+00 – Controls in place and functioning properly. Area stabilized.

☉ 228°SW (T) ● 37°4'31"N, 79°59'3"W ±15637ft ▲ 1592ft



13487

Figure 3: STA 13495+00 – Rill erosion forming in permanently stabilized area. Repair erosion and re-stabilize.

☉ 260°W (T) ● 37°5'19"N, 80°0'20"W ±16ft ▲ 1353ft



Stabilize erosion

13495

Figure 4: STA 13514+00 – Controls in place and functioning properly. Area stabilized.

☉ 108°E (T) ● 37°3'39"N, 79°56'0"W ±11204ft ▲ 1354ft



13514