

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, June 10, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14861+31 – 14981+55 ATWS 376/540/541/377/1364/380	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-SS8, S-CD8, S-AB8, S-DD3, S-G16, S-G15 and S-G13.

Ineffective Controls: (24-Hour Deadline from Notification)

- STA 14870+00: P1 repair needed at Stream S-SS8 crossing.
- STA 14871+50: Waterbar repair needed. Waterbar filled in and does not meet height spec.
- STA 14904+00: Waterbar repair needed. Discharge topping WB causing rilling.

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: Within 24-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: **Wednesday, June 10, 2020**

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, June 10, 2020

Figure 1: STA 14850+00 – Controls in place and functioning properly. Area stabilized with straw and vegetation.

☉ 113°SE (T) ● 36°58'16"N, 79°39'31"W ±16ft ▲ 975ft



Figure 2: STA 14870+00 – P1 repair needed.

☉ 120°SE (T) ● 36°58'15"N, 79°39'27"W ±16ft ▲ 900ft



Figure 3: STA 14871+00 – Water bar repair needed. Does not meet height specification.

☉ 179°S (T) ● 36°58'14"N, 79°39'25"W ±16ft ▲ 907ft



Figure 4: STA 14901+00 – Waterbar repair needed. Discharge overtopping causing rilling.

☉ 56°NE (T) ● 36°58'8"N, 79°38'47"W ±16ft ▲ 855ft

