

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Monday, June 15, 2020	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread I: Franklin County</b>	STA 13539+00 – 13544+00 STA 13627+50 – 13658+80 STA 13676+00 – 13692+00	<b>Weather:</b>	Rainy

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- Tree Felling     
  Clearing/Grubbing     
  Grading     
  Trenching     
  Stringing/Welding  
 Lowering/Backfilling     
  Final Restoration     
  Temp. Stabilization     
  Perm. Stabilization     
 Dormant

- |    |   | Yes                                 | No                                  | N/A                      |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-II7, W-II8, S-II9, E-E28, S-GH3, S-GH4, S-E29 and S-E28.

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** 

**Date:** Monday, June 15, 2020

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Monday, June 15, 2020

**Figure 1: Stream S-II9** – Controls in place and functioning properly.

☉ 75°E (T) ● 37°5'28"N, 79°59'26"W ±16ft ▲ 1315ft



**Figure 2: STA 13632+00** – Controls in place and functioning properly.

☉ 254°W (T) ● 37°5'26"N, 79°57'50"W ±16ft ▲ 1193ft



**Figure 3: STA 13645+00** – Controls in place and functioning properly.

☉ 83°E (T) ● 37°5'21"N, 79°57'37"W ±16ft ▲ 1173ft



**Figure 4: STA 13687+00** – Controls in place and functioning properly.

☉ 345°N (T) ● 37°5'11"N, 79°56'55"W ±16ft ▲ 1147ft

