

FIELD INSPECTION REPORT

| | | | |
|--------------------------------------|--|-------------------------|-----------------------------|
| Project Name: | Mountain Valley Pipeline | Inspector: | Marshall Willis |
| Inspection Date: | Friday, July 24, 2020 | Project Contact: | Brian Clauto, Cory Chalmers |
| Spread I: Franklin County | STA 14209+75 – 14249+19 MVP-FR-311 MVP-MLV-AR-32 | Weather: | Dry |

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-HH4, S-C20, S-C19 and S-F11

Ineffective Controls: (24-Hour Deadline from Notification)

- STA 14222+10: P1 in need of repair.

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: Within 24-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Friday, July 24, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, July 24, 2020

Figure 1: STA 14222+10 – P1 repair needed.

☉ 325°NW (T) ● 37°2'58"N, 79°50'20"W ±7631ft ▲ 1206ft



P1

14222+10

Figure 2: STA 14211+00 – Controls in place and functioning properly.

☉ 5°N (T) ● 37°3'25"N, 79°50'8"W ±32ft ▲ 950ft



14211

Figure 3: Stream S-F11 – Controls in place and functioning properly around Blackwater River crossing.

☉ 103°E (T) ● 37°3'10"N, 79°49'33"W ±16ft ▲ 854ft



S-F11

Figure 4: Stream S-C19 – Controls in place and functioning properly around Maggodee Creek crossing.

☉ 279°W (T) ● 37°3'18"N, 79°49'47"W ±16ft ▲ 865ft



S-C19