

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, July 27, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Pittsylvania County	STA 15947+64 – 16000+00 ATWS 401/401A/1325 Transco Station	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: W-H1, W-H2, S-H3, W-H3, S-H5, S-OO1, W-MM3 and S-OO2.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Monday, July 27, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, July 27, 2020

Figure 1: STA 15949+00 – Controls in place and functioning properly.

☉ 154°SE (T) ● 36°49'33"N, 79°21'35"W ±16405ft ▲ 880ft



15949

Figure 2: STA 15965+00 – Controls in place and functioning properly.

☉ 166°S (T) ● 36°49'57"N, 79°21'33"W ±98ft ▲ 645ft



15965

Figure 3: Stream S-001 – Controls in place and functioning properly around stream crossing.

☉ 124°SE (T) ● 36°49'50"N, 79°21'24"W ±16ft ▲ 607ft



A-001

Figure 4: Stream S-002 – Controls in place and functioning properly around stream crossing.

☉ 133°SE (T) ● 36°49'43"N, 79°21'14"W ±16ft ▲ 652ft



S-002