

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Friday, August 14, 2020	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread I: Franklin County Pittsylvania County</b>	STA 14981+55 – 15063+85 MVP-FR-324 ATWS 380/1283/1284/486/487/382	<b>Weather:</b>	Wet

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- Tree Felling     
  Clearing/Grubbing     
  Grading     
  Trenching     
  Stringing/Welding  
 Lowering/Backfilling     
  Final Restoration     
  Temp. Stabilization     
  Perm. Stabilization     
 Dormant

- |    |   | Yes                                 | No                                  | N/A                      |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-D7, W-MM17, S-D3, S-D4, S-D2, W-D3 and S-D1-INT.

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** 

**Date:** Friday, August 14, 2020

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Friday, August 14, 2020

**Figure 1: STA 14984+00** – Controls in place and functioning properly.

☉ 108°E (T) ● 36°57'55"N, 79°37'10"W ±32ft ▲ 927ft



**Figure 2: STA 14995+00** – Controls in place and functioning properly.

☉ 83°E (T) ● 36°57'51"N, 79°36'57"W ±10797ft ▲ 925ft



**Figure 3: STA 15038+00** – Controls in place and functioning properly.

☉ 76°E (T) ● 36°57'53"N, 79°36'4"W ±98ft ▲ 854ft



**Figure 4: STA 15055+00** – Controls in place and functioning properly.

☉ 305°NW (T) ● 36°57'56"N, 79°35'56"W ±10974ft ▲ 867ft

