

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, August 31, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13846+78 – 13862+60 STA 13949+24 – 13970+00 STA 13995+00 – 14000+00 MVP-FR-303.01/306.02	Weather:	Rainy

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-C16, S-C17, S-CD1, W-CD1 and S-KL36.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Monday, August 31, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, August 31, 2020

Figure 1: STA 13852+00 – Controls in place and functioning properly.

☉ 24°NE (T) ● 37°3'32"N, 79°55'15"W ±32ft ▲ 1127ft



Figure 2: STA 13953+00 – Controls in place and functioning properly.

☉ 275°W (T) ● 37°3'9"N, 79°54'48"W ±14748ft ▲ 1097ft



Figure 3: Stream S-CD1 – Controls in place and functioning properly around S-CD1 crossing.

☉ 272°W (T) ● 37°2'52"N, 79°53'50"W ±164ft ▲ 1109ft



Figure 4: STA 13996+00 – Controls in place and functioning properly. Area stabilized with straw.

☉ 218°SW (T) ● 37°3'11"N, 79°53'4"W ±16ft ▲ 978ft

