

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, August 5, 2020	Project Contact:	Brian Clauto
Spread I: Franklin	MP271.9-273.6 AR-FR314, 315, 622 623 ATWS1272, 526, 526b, 526a, 356, 356a, 358, 358a	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Grading
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

- Comments: Inspected the following resources: W-DD1, S-A41, S-GH36, S-KL17, S-GH37, S-GH38, S-GH39, S-GH40, W-GH16, S-GH44, S-IJ46.
- ECD's were in place and functioning at crossing.

Routine Maintenance: *(72-Hour Deadline from Notification)*

- St14414+00 rill erosion requires repair and stabilization

Ineffective Controls: *(24-Hour Deadline from Notification)*

- N/A.

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: Within 24-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____  _____

Date: Wednesday, August 5, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, August 5, 2020

Figure 1: Designated stream S-A41 noted for repair on 5/4/2020.



Figure 2: Near St14414+00 rill erosion requires repair and stabilization.



Figure 3: ECD's are in place at designated crossing S-IJ46.



Figure 4: Slope drain installed and functioning near MP 273.6

