

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, August 6, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14272+62 – 14411+00 MVP-FR-313/315 ATWS 525/352/353/354/526/622	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-F9b, S-F10, S-F9a, S-GG4, S-A36, S-A36, S-A40, W-DD1 and S-A41.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Thursday, August 6, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, August 6, 2020

Figure 1: Stream S-F9b – Controls in place and functioning properly. Banks stabilized with erosion matting and straw.

⊗ 267°W (T) ● 37°2'57"N, 79°49'1"W ±16ft ▲ 950ft



S-F9b

Figure 2: STA 14319+00 – Controls in place and functioning properly. Area stabilized with straw.

⊗ 119°SE (T) ● 37°2'31"N, 79°48'28"W ±16ft ▲ 1117ft



14319

Figure 3: STA 14351+00 – Controls in place and functioning properly. Area stabilized with straw.

⊗ 120°SE (T) ● 37°2'11"N, 79°48'0"W ±114ft ▲ 1115ft



14351

Figure 4: STA 14373+00 – Controls in place and functioning properly. Area stabilized.

⊗ 128°SE (T) ● 37°2'4"N, 79°47'36"W ±164ft ▲ 977ft



14373