

## FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, September 12, 2018	Project Contact:	Brian Clauto
Spread: Franklin County	Spread I	Weather (Wet/Dry/Rain):	Wet

**STAGE OF CONSTRUCTION:** (Check all that apply)

- Clearing                       Rough Grading                       Trench Excavation                       Pipe Assembly, Testing & Installation  
 Backfilling and Grade Restoration                       Final Grading & Stabilization                       Other: Storm prep


- |   |   | Yes                                 | No                                  | N/A                      |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?   | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |

Comments / Observations:

- **Area 1** – MP 263 slope drain dewatering sump installed at St# 13887+00
- **Area 2** - MP 261 St# 13816+00 sump is full. **Recommended Corrective Action** clean out sump, install adequate sump for drainage area ASAP per site conditions. Sediment below this area has been previously identified.
- **Area 3** - MP 255.40 Cahas Mtn Rd, additional controls have been installed at CE.

**Deadline:** Within 24hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:  Date: 9-17-18

## FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, September 12, 2018

Fig. 1  
MP 263 slope drain dewatering sump installed at St#  
13887+00



Fig. 2  
MP 261 St# 13816+00 sump is full



Fig. 3  
MP255.40 Cahas Mtn Rd, additional controls have been  
installed at CE.



Fig. 4